

JK0-801^{Q&As}

CompTIA A+ Certification Exam (JK0-801)

Pass CompTIA JK0-801 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.leads4pass.com/jk0-801.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





| QUESTION 1 |
|--|
| A technician is installing a new laser printer on a workstation that has Windows 7 Professional x86 installed. |
| Which type of printer driver is needed to complete the installation? |
| A. 16-bit |
| B. 32-bit |
| C. 64-bit |
| D. 86-bit |
| Correct Answer: B |
| |
| |
| QUESTION 2 |
| Which of the following features of Windows allows a device to have a default IP address if a DHCP server is not available? |
| A. APIPA |
| B. ARP |
| C. IPv6 |
| D. DNS |
| Correct Answer: A |
| |
| QUESTION 3 |
| Which of the following display connections has 15-pins? |
| A. RGB |
| B. VGA |
| C. DVI |
| D. HDMI |
| Correct Answer: B |
| |

QUESTION 4

Leads4Pass

https://www.leads4pass.com/jk0-801.html 2024 Latest leads4pass JK0-801 PDF and VCE dumps Download

| A user discovers that color laser prints are printing slightly off-color. |
|---|
| Which of the following should help restore the appropriate colors? |
| A. Use different paper |
| B. Replace the fuser |
| C. Replace the duplexer |
| D. Calibrate the printer |
| Correct Answer: D |
| |
| |
| QUESTION 5 |
| Which of the following would require the need for a POTS line? |
| A. Modem |
| B. Router |
| C. Switch |
| D. Hub |
| Correct Answer: A |
| |
| QUESTION 6 |
| Which of the following is MOST likely needed when installing a new POS thermal printer? |
| A. RJ-11 |
| B. Operating system disk |
| C. RG-58 |
| D. Drivers |
| Correct Answer: D |
| |

QUESTION 7

Which of the following types of Ethernet should be used if a technician has no choice but to run cable along fluorescent lighting arrays in a suspended ceiling?

A. STP

Leads4Pass

https://www.leads4pass.com/jk0-801.html 2024 Latest leads4pass JK0-801 PDF and VCE dumps Download

| B. RG-6 |
|--|
| C. PVC |
| D. UTP |
| Correct Answer: A |
| |
| QUESTION 8 |
| Which of the following would provide continuous power to various devices connected to it during a power surge or outage? |
| A. Line conditioner |
| B. Power strip |
| C. Battery backup |
| D. Surge suppressor |
| Correct Answer: C |
| |
| QUESTION 9 |
| Which of the following 802.11 standards has the MAXIMUM throughput of 11 Mbps? |
| A. A |
| B. B |
| C. G |
| D. N |
| Correct Answer: B |
| |
| QUESTION 10 |
| Which of the following printers is required when carbon paper is used? |
| A. Inkjet |
| B. Thermal |
| C. Laser |
| D. Impact |
| Correct Answer: D |

https://www.leads4pass.com/jk0-801.html 2024 Latest leads4pass JK0-801 PDF and VCE dumps Download

| QUESTION 11 |
|---|
| Which of the following printer types uses an imaging drum? |
| A. Laser |
| B. Impact |
| C. Inkjet |
| D. Thermal |
| Correct Answer: A |
| QUESTION 12 |
| Primary system functions like basic boot priorities, voltage parameters for the processor, and SATA options are configured in which of the following areas of a PC system? |
| A. MBR |
| B. CMOS |
| C. VRAM |
| D. BIOS |
| Correct Answer: D |
| |
| QUESTION 13 |
| A technician has just installed two memory modules on a motherboard that supports DDR3 RAM with the bus speed up to 1600 MHz. The specifications of memory are DDR3 1066 MHz for one module and DDR3 1333 MHz for another. Or which of the following bus speeds will the system function? |
| A. 800 MHz |
| B. 1000 MHz |
| C. 1066 MHz |
| D. 1600 MHz |
| Correct Answer: C |
| |



https://www.leads4pass.com/jk0-801.html

2024 Latest leads4pass JK0-801 PDF and VCE dumps Download

QUESTION 14

Which of the following are the MOST important factors to address when a technician is choosing the components for a CAD workstation? (Select THREE).

- A. Large drive space allocation
- B. Powerful sound card
- C. Multiple network cards
- D. Multiple large HD monitors
- E. Powerful video card
- F. Maximum RAM
- G. Powerful processor

Correct Answer: EFG

QUESTION 15

A user states that when printing to a shared printer nothing happens and the user has verified that the printer is turned on.

Which of the following is the MOST likely cause?

- A. The print server does not have network connectivity.
- B. The ISP service is currently not available.
- C. The user\\'s print drivers are corrupted.
- D. The printer is low on toner.

Correct Answer: A

Latest JK0-801 Dumps

JK0-801 VCE Dumps

JK0-801 Braindumps